



SEAP

NOVINSKI HALL
(DENTAL SCHOOL)

Caution crossing Camino De Salud. Oncoming traffic and emergency vehicles. Post crossing guards as needed.

PEAP

Caution. Emergency vehicles entering.

Caution. Emergency vehicles entering.

PEAP

Caution. Emergency vehicles entering.


Caution. Emergency vehicles entering.

Caution. Emergency vehicles entering.

SEAP

UNMH
PARKING
STRUCTURE

SEAP
UNMH -
If parking
structure is
threatened.



(6-13-12) PROVIDED BY UNM SRS
UTILIZING GOOGLE EARTH IMAGE

DRAWINGS PROVIDED BY:
VINCENT J. LEONARD
UNIVERSITY FIRE MARSHAL

**PRIMARY EVACUATION
ASSEMBLY POINT
(PEAP)**

**SECONDARY inclement
weather, exposure or
danger EVACUATION
ASSEMBLY POINT
(SEAP)**

EXIT ROUTE FROM BUILDING
 ROUTE TO PRIMARY ASSEMBLY POINT
 ROUTE TO SECONDARY ASSEMBLY POINT

**UNM OVERVIEW-
EVACUATION ASSEMBLY POINTS FOR
BUILDING 207 PHYSICS & ASTRONOMY**